

Setter

Z-ZERO

Accessories



Fig.1



Fig.2



Fig.3



Fig.4

Model No.	FIG.	Setting High	Weight (kg)
ZIP50A	1	50mm $\pm$ -0.005	1.30
ASM50	2	50mm $\pm$ -0.005	1.30
ZAP50	3	50mm $\pm$ -0.005	1.00
ZM50A	4	50mm $\pm$ -0.005 (Magnetism/ 有磁性)	1.00
ZM50B	4	50mm $\pm$ -0.005 (No Magnetism/ 無磁性)	1.00

Unit: mm

- Easy, quick and simple for setting tool length on the machine center.
- Base with magnetic.



Fig.1



Fig.2

Model No.	FIG.	Setting High	Weight (kg)
ASM100	1	100mm $\pm$ -0.005	1.80
ANZD100	2	100mm $\pm$ -0.005	2.50

Unit: mm