



▶ Digital measure tape



5500-01

Features

- LCD display.
- There are both inside and outside measurement mode.
- Automatic power off after three minutes without operation.
- Data can be recorded and stored in real time. And it also can retain data and midpoint data.
- There are many different measuring unit.
- Automatic power-on when you pull the tape.

Technical Parameters

- Measuring range: 5 meter
- The wide of the tape: 19mm
- Dimensions: 76mmX72mmX41mm
- Accuracy: 1mm
- Battery type: 2* 3V(CR2032) lithium battery
- Operating temperature: 0~40°C
- Operating humidity: ≤80%
- Storage temperature: -10~60°C

PRODUCT OVERVIEW:

Tape retraction button

To measure a distance using the measuring tape, extract the blade from the housing by pulling on the tab at the end of the blade. The blade will remain at its extracted length, making it easy to hook the tab behind the target. To retract the blade, press tape retraction button.

HOLD/RESET button

HOLD: Press this button for a short time, it will retain the measurement.

RESET: Return the tape to the starting point and press this button for a long time, you could reset the tape to zero.

Unit button

Select/convert units by press this button for a short time.

M+/↔ button

Press this button for a short time to retain measurement. (M1&M2)

Select inside/outside measurement by press this buttons for a long time.

Battery replacement

Press Push back

Two pieces batteries need to be replaced in the same time.

MR button

Press this button for a short time to recall measurement.

↔ button

Midpoint data button by press this button for a long time.