

GAP AND STEP GAUGE / 118-912

Details

1. Used for checking the mutual position or two adjacent surfaces of vehicles.
2. Can measure the gap between two adjacent surface.
3. Small and easy to operate.
4. Power on/off.
5. Mm/inch conversion.
6. Zero setting at any position.

Specifications

Order No.	118-912
Measuring Range	0-20mm
Resolution	0.01mm
Limit Error	+/-0.03mm



GAP AND STEP GAUGE / C1-15P

Specifications

ความถูกต้อง	0.01mm
สี:สีตัววัด	สีแดง
จำนวนรุ่น	C1-15P
Minimum reading value	0.01 mm
Maximum error	0.03 mm
Measuring range	0-30 mm
Working temperature	5 to 45
Working humidity	less than 85
Power supply	1.5 V SR44 button cell



GAP AND STEP GAUGE / C1-20V-A

Specifications

ความถูกต้อง	0.01mm
สี	สีตัววัด:สีแดง
diyuอุปกรณ์	โลหะจำนวน
รุ่น	C1-20V-A
Minimum reading value	0.01 mm
Maximum error	0.03 mm
Measuring range	0-34 mm
Working temperature	5 to 45
Working humidity	less than 85
Power supply	1.5 V SR44 button cell



GAP AND STEP GAUGE / C1-20TF

Specifications

Order No	C1-20TF
Range	0 - ,15, 20, 30 mm
Resoution	0.01 mm



GAP AND STEP GAUGE / C1-20-B

Three Points Digital Step&Gap Gauge Three Half Balls
Three Balls Measuring Surface Digital

Specifications

Order No	C1-20-B
Range	0 - 10, 15 mm
Resoution	0.01 mm



GAP AND STEP GAUGE / C1-20-BM

Specifications

Order No	C1-20-BM
Range	0 - 15, 30 mm
Resoution	0.01 mm



GAP AND STEP GAUGE / 118-901

- adjacent surfaces of vehicles.
- Can measure the gap between two adjacent surfaces.
- Portable and easy to operate.
- Data output.
- Measuring gaps

Specifications

Order No	118-901
Range	0 - 12 mm
Resoution	0.01 mm



GAP AND STEP GAUGE / SG-1

Specifications

Order No	SG-1
Range	0 - 10 mm
Resoution	0.05 mm

