

# **STEP GAUGES**

## RIVSG / RIVSG-SPC

# **Step Gauges**

Rivet and Step Gauge w/ Non-Marring Contacts. With optional USB cable, SPC models can input data directly to MS Excel

- Measures panel flush, rivet heights & weld heights
- Ideal tool for the aerospace or auto industry
- Non-Marring
- Converts to measure step height
- Great as a high speed, accurate go no go gauge
- Transfer data to an ASI Datamyte® or LMI Data
- Collector® or laptop (OPTIONAL)

#### **TECH NICAL SPECIFICATIONS**

Measuring Range	0 to 5mm / 0 to 0.1970in.
Max Rivet Diameter	12.7mm / 0.5000in.
Resolution	0.01mm / 0.0005in.
Accuracy	± 0.02mm / 0.001in.
Repeatability	0.01mm / 0.0005in.



# **STEP GAUGES**

SG3-LR

## **Step Gauges**

Basic Step Gauge Economically Priced w/ Non-Marring Left and Right Arms Included

- Measure checking fixture flushness
- Measure panel to panel flushness
- Stable on uneven or curved surfaces
- Left & Right hand adjustable arms
- Data transfer (OPTIONAL)

#### **TECH NICAL SPECIFICATIONS**

Measuring Range	-6mm to +11mm
Resolution	0.01mm
Accuracy	± 0.03mm



0